



FIGURES



BASEMAP: PORTIONS OF THE FOLLOWING U.S.G.S. QUADRANGLE MAPS: BRIDGEPORT, CONN., 1970 (PHOTOREVISED: 1984) AND MILFORD, CONN., 1960 (PHOTOREVISED: 1984), SCALE ALTERED FOR CLARITY



SITE LOCUS - RAYMARK - OU3

REMEDIAL ALTERNATIVES SCREENING REPORT

STRATFORD, CONNECTICUT

DRAWN BY: D.W. MACDOUGALL

REV.: 0

PROJECT MANAGER: H. FORD

DATE: NOVEMBER 2000

SCALE: AS SHOWN

ACAD NAME: DWG\RAYMARK\7491\1010\OU3.DWG

FIGURE 1-1




TETRA TECH NUS, INC.

55 Jonspin Road









Wilmington, MA 01887


(978)658-7899



400 0 400 800 1200 1600 Feet

NOTES:
 1) ALL LOCATIONS AND BOUNDARIES TO BE CONSIDERED APPROXIMATE
 2) PLAN NOT TO BE USED FOR DESIGN

- | | | |
|---|--|-----------------|
|  | RAYMARK FACILITY | OPERABLE UNIT 1 |
|  | UPPER FERRY CREEK AND WETLANDS | OPERABLE UNIT 3 |
|  | RAYBESTOS MEMORIAL FIELD | OPERABLE UNIT 4 |
|  | SHORE ROAD AREA | OPERABLE UNIT 5 |
|  | COMMERCIAL PROPERTIES | OPERABLE UNIT 6 |
|  | LOWER FERRY CREEK, SELBY POND
AND HOUSATONIC RIVER WETLANDS | OPERABLE UNIT 7 |
|  | BEACON POINT BOAT LAUNCH AREA
AND ELM STREET WETLANDS | OPERABLE UNIT 8 |
|  | GROUNDWATER | OPERABLE UNIT 2 |

RAYMARK OPERABLE UNITS		FIGURE 1-2	
REMEDIAL ALTERNATIVES SCREENING REPORT OPERABLE UNIT 3			TETRA TECH NUS, INC.
RAYMARK INDUSTRIES, INC. SUPERFUND SITE STRATFORD, CONNECTICUT			
DRAWN BY: D. A. CHISHOLM	DATE: NOVEMBER 14, 2000		
SCALE: AS SHOWN	FILE: JALLRAY.APR	55 JONSPIN ROAD (978)858-7899	WILMINGTON, MA 01887

REFERENCES

REFERENCES

- Halliburton NUS Corporation (HNUS), 1995. *Final Remedial Investigation Report, Remedial Investigation/Feasibility Study, Raymark Industries, Inc. Facility, Stratford, Connecticut*. April.
- Halliburton NUS Corporation (HNUS), 1994a. *Final Treatability Study Report for Bench Scale Solidification and Stabilization, Remedial Investigation, Raymark Industries, Inc. Site, Stratford, Connecticut*. August.
- Halliburton NUS Corporation (HNUS), 1994b. *Final Treatability Study Report for Bench Scale Thermal Treatment, Remedial Investigation, Raymark Industries, Inc. Site, Stratford, Connecticut*. October.
- Longest, Henry L. 1989. Analysis of Treatability Data for Soil and Debris: Evaluation of Land Ban Impact on Use of Superfund Treatment Technologies. Office of Emergency and Remedial Response. OSWER Directive 9380.3-04. November.
- RS Means. 1998. Heavy Construction Cost Data Book. 12th Edition. published by RS Means Co.
- RS Means. 1998. Environmental Remediation Unit Cost Book, published by RS Means Co. 1998.
- Tetra Tech NUS (TtNUS). 2000. *Final Remedial Investigation Raymark – Operable Unit 2 – Groundwater*. November.
- Tetra Tech NUS (TtNUS). 1999. *Draft Final Remedial Investigation Raymark – Ferry Creek – Operable Unit 3*.
- U.S. Environmental Protection Agency. 1998. Approaches for Addressing Dioxins in Soil at CERCLA and RCRA Sites. OSWER Directive 9200.4-26. April 13.

U.S. Environmental Protection Agency. 1994. Revised Interim Guidance on Establishing Soil Lead Guidance for CERCLA Sites and RCRA Corrective Action Facilities. OSWER Directive 9355.4-12. July 14.

U.S. Environmental Protection Agency. 1994. "ARCS Remediation Guidance Document." EPA-905-B94-003. Great Lakes National Program Office, Chicago, IL.

U.S. Environmental Protection Agency, 1993. CERCLA Off-Site Rule, EPA OSWER Directive 9834.11. October.

U.S. Environmental Protection Agency, 1990. Solidification. EPA/540/5-89/005G.

U.S. Environmental Protection Agency. 1989. *Soliditech, Inc. Solidification*, EPA RREL, series includes Technology Evaluation, Vol. I, EPA/540/5-89/005a.

U.S. Environmental Protection Agency. 1989. *Hazcon Solidification*, EPA RREL, series includes Technology Evaluation, Vol. I, EPA/540/5-89/001a.

U.S. Environmental Protection Agency. 1988. CERCLA Compliance with Other Laws Manual: Part 1 (Interim Final), OSWER Directive No. 9234.1-01, EPA/540/G-89/006.

U.S. Environmental Protection Agency. 1988. Guidance for Conducting Remedial Investigations and Feasibility Studies under CERCLA. EPA/540/G-89/004. October.

U.S. Environmental Protection Agency. 1985. Remedial action at waste disposal sites (revised). EPA/625/6-85/006. U.S. Environmental Protection Agency, Hazardous Waste Engineering Research Laboratory, Cincinnati, OH.